


# SECTION 7: PARTS

## Parts Breakdown & List



| REF | PART #   | DESCRIPTION             |
|-----|----------|-------------------------|
| 1   | P7147001 | BENDING ASSEMBLY        |
| 2   | P7147002 | SHAFT                   |
| 3   | P7147003 | BODY                    |
| 4   | P7147004 | CLAMPING PLATE ASSEMBLY |
| 5   | P7147005 | ECCENTRIC SHAFT         |
| 6   | P7147006 | CONNECTING BLOCK        |
| 7   | PW03M    | FLAT WASHER 6MM         |
| 8   | PSB68M   | CAP SCREW M6-1 X 8      |
| 9   | PN02M    | HEX NUT M10-1.5         |
| 10  | P7147010 | TURNBUCKLE M10-1.5      |
| 11  | PN02M    | HEX NUT M10-1.5         |
| 12  | P7147012 | BUSHING                 |

|      |            |                                 |
|------|------------|---------------------------------|
| 13A  | P7147013A  | RIGHT ECCENTRIC SHAFT 11MM-1.75 |
| 14-1 | P7147014-1 | COMPLETE HANDLE ASSEMBLY        |
| 14A  | P7147014A  | HANDLE SHAFT 11MM-1.75          |
| 15   | P7147015   | HANDLE                          |
| 16   | P7147016   | CLEVIS PIN 14 X 40              |
| 17   | P7147017   | COTTER PIN 2.5 X 35             |
| 18   | PSB03M     | CAP SCREW M5-.8 X 8             |
| 19   | P7147019   | FLAT KEY                        |
| 20   | P7147020   | BUSHING                         |
| 21   | P7147021   | SMALL SHAFT                     |
| 22   | P7147022   | LEFT ECCENTRIC SHAFT            |

